2" BSP Threaded ATCO™
ND50 Ball Valve
AD5X7T

MAINTENANCE

ITEM	QTY	DESIGNATION	PART N°
		Ball seals kit:	**11 14 75 90 00**
2	1	Ball seal (PTFE)	11 12 39 00 09
17	1	Base gasket (PTFE)	11 14 73 00 01
		Ball kit:	**11 12 42 91 00**
4	1	Ball (316)	11 12 42 00 11
		Drilled Ball kit:	**11 12 39 94 00**
4	1	Drilled Ball (316)	11 12 39 00 11
		Handle kit:	**11 14 16 92 00**
12	1	Handle (st st)	-
	1	Handle cap, nitrile	-
10	2	M16 Nut	-
11	1	Stop washer	-
13	1	Washer Nordlock Ø 16	-
		Spindle seals kit:	**11 12 42 93 00**
6	1	Bearing Bush (PTFE)	11 12 39 00 14
5	1	O'Ring (FEP/silicone)	70 10 15 00 12
4	1	Spindle Gasket	11 12 39 00 21
		Spindle kit:	**on request**
3	1	Spindle (St st)	11 12 39 00 16
9	2	Elastic washer (St st)	-
8	1	Washer (St st)	-
		Filter kit:	**11 14 75 92 00**
23	1	Filter (St st)	11 12 03 20 00
24	1	Lock Ring (St st)	70 13 14 37 08
		2" Cap kit:	
18	1	2" BSP Cap + Seal + Chain	11 14 64 20 00
18	1	2" NPT Cap + Seal + Chain	11 14 75 20 00
-	1	Cap seal (PTFE)	11 12 03 40 02
		Tools kit:	**11 12 69 94 00**
A	1	Spindle Assembly tool	11 12 69 92 01
B	1	O'Ring Assembly tool	11 12 69 92 02

Nb Perolo recommends :
- The spindle seals should be changed simultaneously to maintain the ball valve spindle perfectly tight.
- Both ball gaskets should be changed
-Valve should be in closed position during installation





AIR LINE

PEROLO SAS, 69 Rue des Maçons, 33390 Blaye, FRANCE -Phone : + 33 (0)5 5742 67 00 - Email : sales@perolo.com