

MAINTENANCE

ITEM	QTY	DESIGNATION	PART N°	
			Standard	High Temp
Ball seals kit:			11 12 52 92 00	11 14 09 91 50
14	2	Ball seals (PTFE / PTFE/Graphite)	11 12 71 00 07	11 12 71 00 09
17	1 / 2	O'ring (FEP / PFA)	70 10 15 00 92	70 10 17 00 50
18	1	O'ring (Viton)	70 10 01 02 49	/
Spindle seals kit:			11 12 52 93 00	11 14 09 92 50
5	1	Bearing bush (PTFE)	11 12 52 00 09	11 12 71 00 10
4	1	O'ring (FEP encapsulated)	70 10 15 00 91	70 10 17 00 60
3	1	Spindle seal (PTFE)	11 12 52 00 10	11 12 71 00 11
Ball kit:			11 12 52 91 00	
15	1	Ball (stainless steel)	11 12 52 00 051	
Spindle:				
2	1	Spindle (stainless steel)	11 12 52 00 24	
Bolting:				
6	1	Washer (stainless steel)	70 13 25 37 24	
7	2	Elastic washer (stainless steel)	70 13 26 37 09	
20	1	Washer (stainless steel)	70 13 26 37 18	
Handle kit:			11 12 71 98 00	
10	1	Handle (stainless steel)	11 14 05 00 28	
	1	Handle cap, Nitrile	-	
8	1	Nuts (stainless steel)	-	
9	2	Stop washer (stainless steel)	-	
Clamping ring kit:			11 12 71 90 00	
16	1	Clamping ring (stainless steel)	-	
19	6	Screws M6 (stainless st.)	-	
Tools kit:			11 12 71 96 00	
A	1	Spindle assembly tool	11 12 71 93 01	
B	1	O'ring assembly tool	11 12 71 93 02	

Material of the parts are indicated for Stainless Steel Version.
It may vary in HALAR Coated version.
Please refer to HIGH CORROSION Catalogue for more details

Nb: Perolo recommends

- the spindle seals should be changed simultaneously to maintain the ball valve spindle perfectly tight.
- both ball gaskets should be changed simultaneously
- when clamping ring is changed we recommend to also order ball seals kit

